

Contents

Chapter 1: “Z” Basics

- 1.1 The UCS Icon and the Right-Hand Rule 4
 - 1.1.1 The UCS Icon 4
 - 1.1.2 The Right-Hand Rule 8
- 1.2 Maneuvering Through Z-Space with the *VPoint* Command 8
 - 1.2.1 Using Coordinates to Assign a Vpoint 8
 - 1.2.2 Using the Compass to Assign a Vpoint 12
 - 1.2.3 Setting Viewpoints Using a Dialog Box 14
 - 1.2.4 The Camera Approach 17
- 1.3 Drawing with the Z-Axis 19
 - 1.3.1 Three-Dimensional Coordinate Entry 19
 - 1.3.2 Using the Thickness and Elevation System Variables 22
- 1.4 Three-Dimensional Viewing Made Easy 26
 - 1.4.1 The *Hide* Command 26
 - 1.4.2 The *Shademode* Command 28
- 1.5 Extra Steps 33
- 1.6 What Have We Learned? 33
- 1.7 Exercises 34

Chapter 2: More of Z Basics

- 2.1 WCS vs. UCS 43
- 2.2 The UCS Dialog Box (Manager) 51
- 2.3 Using Working Planes 53
- 2.4 Advanced Viewing Techniques 59
 - 2.4.1 3DOrbit 59
 - 2.4.2 A Continuous Three-Dimensional Orbit – *3DCOrbit* 68
- 2.5 Extra Steps 69
- 2.6 What Have We Learned? 69
- 2.7 Exercises 70

Chapter 3: Wireframes and Surface Models

- 3.1 *3DPoly* vs. *PLine* 78
- 3.2 Drawing in Three Directions at Once – Point Projection 78
- 3.3 Adding Surfaces – Regions, Solids, and 3D Faces 81
 - 3.3.1 Creating 3D Faces 81
 - 3.3.2 Invisible Edges in 3D Faces – *SPLFrame* and the *Edge* Command 84
 - 3.3.3 Solids and Regions 86
 - 3.3.4 Which Method Should You Use? 92
- 3.4 Extra Steps 93
- 3.5 What Have We Learned? 95
- 3.6 Exercises 95

Chapter 4: Predefined Surface Models

- 4.1 What Are Predefined Surface Models? 102
- 4.2 Drawing Predefined Surface Models 103
 - 4.2.1 Box 103
 - 4.2.2 Wedge 105
 - 4.2.3 Pyramid 106
 - 4.2.4 Cone 110
 - 4.2.5 Sphere 112
 - 4.2.6 Domes and Dishes 113
 - 4.2.7 Torus 115
- 4.3 Understanding the Limitations of Predefined Surface Models 116
- 4.4 Extra Steps 117
- 4.5 What Have We Learned? 117
- 4.6 Exercises 118

Chapter 5: Complex Surface Models

- 5.1 Controlling the Number of Surfaces – *Surftab1* and *Surftab2* 125
- 5.2 Different Approaches for Different Goals 126
 - 5.2.1 Follow the Path – The *Tabsurf* Com'd 126
 - 5.2.2 Add a Surface Between Objects – The *Rulesurf* Command 129
 - 5.2.3 Creating Circular Surfaces – The *Revsurf* Command 131
 - 5.2.4 Using Edges to Define a Surface Plane – The *Edgesurf* Command 133
- 5.3 More Complex Surfaces 135
 - 5.3.1 Creating Meshes with the *3DMesh* Command 136
 - 5.3.2 Creating Meshes with the *PFace* Command 138
- 5.4 Extra Steps 142
- 5.5 What Have We Learned? 143
- 5.6 Exercises 144

Chapter 6: Z-Space Editing

- 6.1 Three-Dimensional Uses for Familiar (Two-Dimensional) Tools 151
 - 6.1.1 Trimming and Extending in Z-Space 151
 - 6.1.2 Aligning Three-Dimensional Objects 157
 - 6.1.3 Three-Dimensional Object Properties 158
 - 6.1.4 Modifying a 3D Mesh 161
- 6.2 Editing Tools Designed for Z-Space 170
 - 6.2.1 Rotating About an Axis – The *Rotate3d* Command 170
 - 6.2.2 Mirroring Three-Dimensional Objects – The *Mirror3d* Command 173

- 6.2.3 Arrayed Copies in Three Dimensions – The *3DArray* Command 177
- 6.3 Extra Steps 181
- 6.4 What Have We Learned? 181
- 6.5 Exercises 182

Chapter 7: Solid Modeling Building Blocks

- 7.1 What Are Solid Modeling Bldg Blocks? 187
- 7.2 Extruding 2D Regions and Solids 187
- 7.3 Drawing the Solid Modeling Bldg Blocks 191
 - 7.3.1 Box 191
 - 7.3.2 Wedge 193
 - 7.3.3 Cones and Cylinders 195
 - 7.3.4 Sphere 198
 - 7.3.5 Torus 199
- 7.4 Creating More Complex Solids Using the *Revolve* Command 201
- 7.5 Extra Steps 204
- 7.6 What Have We Learned? 205
- 7.7 Exercises 205

Chapter 8: Composite Solids

- 8.1 Solid Construction Tools 212
 - 8.1.1 Union 213
 - 8.1.2 Subtract 214
 - 8.1.3 Intersect 216
 - 8.1.4 Slice 217
 - 8.1.5 Interfere 222
- 8.2 Using Some Old Friends on Solids – *Fillet* and *Chamfer* 224
- 8.3 Creating Cross Sections the Easy Way – The *Section* Command 227
- 8.4 Extra Steps 229
- 8.5 What Have We Learned? 229
- 8.6 Exercises 230

Chapter 9: Editing 3D Solids

- 9.1 A Single Command, But It Does So Much - *SolidEdit* 238
- 9.2 Changing Faces – The Face Category 238
 - 9.2.1 Changing the Thickness of a 3D Solid Face – the *Extrude* Option 239
 - 9.2.2 Moving a Face on a 3D Solid 241
 - 9.2.3 Rotating Faces on a 3D Solid 243
 - 9.2.4 Offsetting Faces on a 3D Solid 245
 - 9.2.5 Tapering Faces on a 3D Solid 246
 - 9.2.6 Deleting 3D Solid Faces 248
 - 9.2.7 Copying 3D Solid Faces as Regions or Bodies 249

- 9.2.8 Changing the Color of a Single Face 251
- 9.3 Modifying Edges – The Edge Category 252
- 9.4 Changing the Whole 3D Solid – The Body Category 254
 - 9.4.1 Imprinting an Image onto a 3D Solid 255
 - 9.4.2 Separating 3D Solids with the *separate* Solids Routines 257
 - 9.4.3 Clean 258
 - 9.4.4 Shell 259
 - 9.4.5 Checking to Be Certain You Have an ACIS Solid 260
- 9.5 Extra Steps 261
- 9.6 What Have We Learned? 261
- 9.7 Exercises 262

Chapter 10: Three-Dimensional Blocks and Three-Dimensional Plotting Tools

- 10.1 Using Blocks in Z-Space 270
 - 10.1.1 Three-Dim. Blocks and the UCS 270
 - 10.1.2 Inserting Three-Dimensional Blocks 271
 - 10.1.3 Making Good Use of Attributes 275
- 10.2 Plotting a 3D Solid 277
 - 10.2.1 Setting Up the Plot – the *Solview* Command 277
 - 10.2.2 Creating the Plot Images – The *Soldraw* and *Solprof* Commands 283
- 10.3 Extra Steps 287
- 10.4 What Have We Learned? 287
- 10.5 Exercises 288

Chapter 11: Is It Real or Is It Rendered?

- 11.1 What Is Rendering and Why Is It So Challenging? 297
- 11.2 Beyond Shademode – The *Render* Com'd 297
- 11.3 Adding Materials to Make Your Solids Look Real 308
- 11.4 Special Effects – Adding Other Graphic Images to Your Drawing 316
- 11.5 Lights 321
- 11.6 Creating a Scene 329
- 11.7 Extra Steps 332
- 11.8 What Have We Learned? 332
- 11.9 Exercises 333

Appendices

- Appendix – A: Drawing Scales 338
- Appendix – B: Project Drawings 339
- Appendix – D: Additional Projects 342